

An aerial photograph of a road interchange and surrounding landscape, featuring a large circular interchange and several straight road segments cutting through a wooded area.

RRL Report LR 232

ROAD RESEARCH LABORATORY

MINISTRY of TRANSPORT

CORROSION OF MOTOR VEHICLES BY DE-ICING SALT — RESULTS OF A SURVEY

R. R. Bishop, Ph.D., B.Sc.